

# **BUILDING REPORT REQUIREMENTS ASCE 41-17 TIER 1 SEISMIC EVALUATIONS**

### **BUILDING REPORT**

1) UC Campus: Los Angeles


2) Building Name: Lake Arrowhead Cedar

3) Building CAAN ID: 4201X 4) Auxiliary Building ID:

5) Date of Evaluation: 6/30/2020 6) Evaluation by: Englekirk, TAS

7) Seismic Performance Rating and Basis of

Rating: VI, ASCE 41-17 Tier 1





9) Exterior Elevation Photo

8) Plan Image or Aerial Photo

10) Site Location

(a) Latitude Decimal Coordinates: 34.2664

(b) Longitude Decimal Coordinates: -117.185565

11) ASCE 41-17 Model Building Type and Description

(a) Longitudinal Direction: W1a: Wood frame, wood shear panels

(b) Transverse Direction: W1a: Wood frame, wood shear panels

12) Number of Stories

(a) Above grade: 2

(b) Below grade: 1

- 13) Original Building Design Code & Year:
- 14) Retrofit Building Design Code & Year (if applicable):
- 15) Cost Range to Retrofit (if applicable): (Low, Medium, High or Very High): Medium

Comments: No drawings. Cannot confirm via field visit unstiffened cripple walls and lack of bolting to foundation wall, but assumed to be deficient.



#### **BACKGROUND INFORMATION**

#### **Site Information**

16) Site Class (A – F) and Basis of Assessment

(a) Site Class:

(b) Site Class Basis: Unknown (Default)

(c) Site Class Company: None(d) Site Class Report Date: None(e) Site Class Ref Page No.: None

17) Geologic Hazards

(a) Fault Rupture (Yes, No or Unknown) and Basis of Assessment: Unknown, None

(b) Liquefaction (Yes, No or Unknown) and Basis of Assessment: Unknown, None

(c) Landslide (Yes, No or Unknown) and Basis of Assessment: Unknown, None

18) Site-specific Ground Motion Study? (Yes or No) No

Seismic design acceleration parameters of interest:	
For BSE-1N	1.249 and 0.805
For BSE-1E	0.919 and 0.545

19) Estimated Fundamental Period (seconds)

(a) Longitudinal: 0.19(b) Transverse: 0.19

20) Falling Hazards Assessment Summary: None noted.

- 21) Structural Non-Compliances/Findings Significantly Affecting Rating Determination Summary Significant Structural Deficiencies, Potentially Affecting Seismic Performance Rating Designation:
  - (a) Lateral System Stress Check (wall shear, column shear or flexure, or brace axial as applicable): Yes, wall shear stress deficiency noted
  - (b) Load Path: Yes, deficiency noted
  - (c) Adjacent Buildings: No deficiency noted
  - (d) Weak Story: No deficiency noted
  - (e) Soft Story: No deficiency noted
  - (f) Geometry (vertical irregularities): No deficiency noted
  - (g) Torsion: Not Applicable
  - (h) Mass Vertical Irregularity: No deficiency noted
  - (i) Cripple Walls: Yes, deficiency noted
  - (j) Wood Sills (bolting): Yes, deficiency noted
  - (k) Diaphragm Continuity: No deficiency noted
  - (I) Openings at Shear Walls (concrete or masonry): Not Applicable
  - (m) Liquefaction: Unknown(n) Slope Failure: Unknown



(o) Surface Fault Rupture: Unknown

(p) Masonry or Concrete Wall Anchorage at Flexible Diaphragm: Not Applicable

(q) URM wall height to thickness ratio: No deficiency noted

(r) URM Parapets or Cornices: Not Applicable

(s) URM Chimney: Not Applicable

(t) Heavy Partitions Braced by Ceilings: No deficiency noted

(u) Appendages: No deficiency noted

## 22) Brief Description of Anticipated Failure Mechanism

Unbraced cripple walls and lack of perimeter wall bolting at foundation assumed to exist. Failure of letin or diagonal bracing or exterior stucco and interior plaster walls,

23) Seismic Retrofit Concept Sketches/Description (only required for buildings rated V or worse) Add new concrete interior foundations and anahcorage hardware. Secure perimeter walls to foundations and brace with plywood. Connect crawl space framing with structural hardware and strapping. Add new shear walls. Anchor roof framing to exterior walls. Resheath roof with plywood. Connect roof framing with structural hardware.

# **Building Report Appendices**

- A) ASCE 41-17 Tier 1 Checklists (Structural only)
- B) Quick Check Calculations