



BUILDING REPORT REQUIREMENTS
ASCE 41-17 TIER 1 SEISMIC EVALUATIONS

BUILDING REPORT

- 1) UC Campus: Los Angeles
2) Building Name: Lake Arrowhead Maintenance Building
3) Building CAAN ID: 4201B
4) Auxiliary Building ID:
5) Date of Evaluation: 6/30/2020
6) Evaluation by: Englekirk, TAS
7) Seismic Performance Rating and Basis of Rating: V, ASCE 41-17 Tier 1




8) Plan Image or Aerial Photo



9) Exterior Elevation Photo

- 10) Site Location
(a) Latitude Decimal Coordinates: 34.26653
(b) Longitude Decimal Coordinates: -117.18521
11) ASCE 41-17 Model Building Type and Description
(a) Longitudinal Direction: W1 and W2: Wood frame, wood shear panels
(b) Transverse Direction: W1 and W2: Wood frame, wood shear panels
12) Number of Stories
(a) Above grade: 1
(b) Below grade: 0
13) Original Building Design Code & Year:
14) Retrofit Building Design Code & Year (if applicable):
15) Cost Range to Retrofit (if applicable): (Low, Medium, High or Very High): Low



Comments: This is called Facility 1. No drawings provided. UCLA records indicate building constructed in 1971. There are drawings for the adjacent Facility 2, which has a similar appearance. There is a mezzanine level. No tension member to tie walls/roof joists together at middle section. Limited shear wall length in the east&west elevations due to large door/window openings. The diaphragm sheathing of the mezzanine



consists of straight sheathing, not plywood or diagonal sheathing, and doesn't extend to the exterior walls, which creates a diaphragm discontinuity. There is no shear blocking between the roof/floor joists to transfer the diaphragm load to the exterior walls.

BACKGROUND INFORMATION

Site Information

16) Site Class (A – F) and Basis of Assessment

- (a) Site Class: **D**
- (b) Site Class Basis: **Unknown (Default)**
- (c) Site Class Company: **None**
- (d) Site Class Report Date: **None**
- (e) Site Class Ref Page No.: **None**

17) Geologic Hazards

- (a) Fault Rupture (Yes, No or Unknown) and Basis of Assessment: **No, San Bernardino County Land Use Map**
- (b) Liquefaction (Yes, No or Unknown) and Basis of Assessment: **No, San Bernardino County Land Use Map**
- (c) Landslide (Yes, No or Unknown) and Basis of Assessment: **No, San Bernardino County Land Use Map**

18) Site-specific Ground Motion Study? (Yes or No) **No**

Seismic design acceleration parameters of interest:	
For BSE-1N	1.249 and 0.805
For BSE-1E	0.919 and 0.545

19) Estimated Fundamental Period (seconds)

- (a) Longitudinal: **0.16**
- (b) Transverse: **0.16**

20) Falling Hazards Assessment Summary: **None noted except unanchored building contents**

21) Structural Non-Compliances/Findings Significantly Affecting Rating Determination Summary
Significant Structural Deficiencies, Potentially Affecting *Seismic Performance Rating* Designation:

- (a) Lateral System Stress Check (wall shear, column shear or flexure, or brace axial as applicable):
Yes, wall shear stress deficiency noted
- (b) Load Path: **Yes, deficiency noted**
- (c) Adjacent Buildings: **No deficiency noted**
- (d) Weak Story: **No deficiency noted**
- (e) Soft Story: **No deficiency noted**
- (f) Geometry (vertical irregularities): **No deficiency noted**
- (g) Torsion: **Not Applicable**
- (h) Mass – Vertical Irregularity: **No deficiency noted**



- (i) Cripple Walls: No deficiency noted
- (j) Wood Sills (bolting): No deficiency noted
- (k) Diaphragm Continuity: No deficiency noted
- (l) Openings at Shear Walls (concrete or masonry): Not Applicable
- (m) Liquefaction: No
- (n) Slope Failure: No
- (o) Surface Fault Rupture: No
- (p) Masonry or Concrete Wall Anchorage at Flexible Diaphragm: Not Applicable
- (q) URM wall height to thickness ratio: Not Applicable
- (r) URM Parapets or Cornices: Not Applicable
- (s) URM Chimney: Not Applicable
- (t) Heavy Partitions Braced by Ceilings: No deficiency noted
- (u) Appendages: No deficiency noted

22) Brief Description of Anticipated Failure Mechanism

Failure of shear wall panels and nailing, hold-downs and/or compression posts. Excessive out-of-plane wall deflection due to lack of tension tie/diaphragm at top plate at middle portion of building.

23) Seismic Retrofit Concept Sketches/Description (only required for buildings rated V or worse)

Provide hold-downs and additional shear walls. Stiffen or tie top plate for out-of-plane loads where tension ties not provided.

Building Report Appendices

- A) ASCE 41-17 Tier 1 Checklists (Structural only)
- B) Quick Check Calculations