

Krieger CTR - B

DATE: 10/27/2020 ASCE 41-17 Tier 1 Seismic Evaluation Minimum Building Report Information

BUILDING DATA

Campus: UCLA Building Name: Krieger CTR-B CAAN ID: 4399 Auxiliary Building ID: 4399B Address: 101 Bellagio Drive, Los Angeles 90024 Site location coordinates: Latitude 34.07556671 Longitudinal -118.4551378



ASCE 41-17 Model Building Type:

- a. Longitudinal Direction: S1a Steel Moment Resisting Frame with Flexible Diaphragm
- b. Transverse Direction: S1a Steel Moment Resisting Frame with Flexible Diaphragm

Site-specific Ground Motion Study? No Seismic Design Acceleration Parameters of Interest (S_{xs} and S_{x1}):

- a. For BSE-1E 0.895g and 0.515g
- b. For BSE-2E 1.836g and 0.94g

Estimated Fundamental Period (seconds)

- a. Longitudinal: 0.1s
- b. Transverse: 0.1s



Gross Square Footage: 3,790 Number of stories *above* grade: 1 Number of basement stories *below* grade: 0

Year Original Building was Constructed: 1987 Original Building Design Code & Year: UBC-1985 Retrofit Building Design Code & Code (if applicable): N/A, N/A

SITE INFORMATION

Site Class: D (Measured)	Basis:	Geotechnologies, Inc. , 10/21/2002, Pg. 15
Geologic Hazards:		
Fault Rupture: No	Basis:	Referenced Geotechnical Report
Liquefaction: No	Basis:	Referenced Geotechnical Report
Landslide: No	Basis:	Referenced Geotechnical Report

BUILDING COMPLEX KEY PLAN

The Kriger CTR complex is composed of three buildings. Shown below is a key plan of the complex along with the distribution of Building ID's at the complex.



Figure 1 Key Plan of the Krieger CTR complex

UCOP SEISMIC PERFORMANCE RATING (OR "RATING"): V

"BALLPARK" RETROFIT COST (if applicable)

Minor (<\$50/sf)</p>

- Moderate (~\$50-\$200/sf)
- Major (>\$200/sf)

SUMMARY TIER 1 SEISMIC EVALUATION STRUCTURAL NON-COMPLIANCES/FINDINGS SIGNIFICANTLY AFFECTING RATING DETERMINATION

Significant Structural Deficiencies, Potentially Affecting Seismic Performance Level Designation:

- \boxtimes Lateral System Stress Check (wall shear, column shear or flexure, or brace axial as applicable)
- \boxtimes Lateral System Detailing (reinforcement ratio, confinement, aspect ratio, etc)
- \boxtimes Load Path
- **Adjacent Buildings**
- Weak Story
- Soft Story
- Geometry (vertical irregularities)
- Torsion
- Mass – Vertical Irregularity
- **Cripple Walls**
- Wood Sills (bolting)
- **Diaphragm Continuity**
- Openings at Shear Walls (concrete or masonry)
- Liquefaction
- **Slope Failure**
- Surface Fault Rupture
- Masonry or Concrete Wall Anchorage at Diaphragm
- URM wall height to thickness ratio
- **URM Parapets or Cornices**
- **URM Chimney**
- Heavy Partitions Braced by Ceilings
- Appendages

BRIEF DESCRIPTION OF ANTICIPATED FAILURE MECHANISM

Building light gage modular construction. Drawings do not detail foundations or attachment, so rating has assumed no connection to the foundation which is a common deficiency for buildings of this type. Superstructure relies on moment frame action of light gage tubes and C-shape joists, which does not pass Tier 1 quick checks for moment frame drift. Building would rate V regardless of connection to foundation.

COMMENTS AND RECOMMENDATIONS

Building is unlikely to rate higher than V without retrofit based on light gage construction, so Tier 2 evaluation is not recommended. Connection to foundation should be investigated with more detailed field observations.

POTENTIAL FALLING HAZARDS

- Heavy ceilings, features or ornamentation above large lecture halls, auditoriums, lobbies or other areas where large numbers of people congregate.
- Heavy masonry or stone veneer above exit ways.
- Unbraced masonry parapets, cornices or other ornamentation above exit ways.
- Unrestrained hazardous materials storage.
- Masonry chimneys.
- Unrestrained natural gas-fueled equipment such as water heaters, boilers, emergency generators, etc.
- ⊠ None of the above.

Appendices

- A. ASCE 41-17 Tier 1 Checklists
- B. Quick Check Calculations