

BUILDING REPORT REQUIREMENTS ASCE 41-17 TIER 1 SEISMIC EVALUATIONS

BUILDING REPORT

1) UC Campus: Los Angeles


2) Building Name: Young Hall, Building C-1

3) Building CAAN ID: 4228B4) Auxiliary Building ID: 4228B.2


5) Date of Evaluation: 12/4/20206) Evaluation by: Englekirk, TAS / NAT

7) Seismic Performance Rating and Basis of

Rating: V, ASCE 41-17 Tier 1



8) Plan Image or Aerial Photo



9) Exterior Elevation Photo

10) Site Location

(a) Latitude Decimal Coordinates: 34.0688448(b) Longitude Decimal Coordinates: -118.441199

11) ASCE 41-17 Model Building Type and Description

(a) Longitudinal Direction: C2 and C2a: Reinforced concrete shear walls

(b) Transverse Direction: C2 and C2a: Reinforced concrete shear walls

12) Number of Stories

(a) Above grade: 5 (b) Below grade: 1

13) Original Building Design Code & Year: UBC-1949

14) Retrofit Building Design Code & Year (if applicable):

15) Cost Range to Retrofit (if applicable): (Low, Medium, High or Very High): Medium

SE 3175 PUCTURAL TO CALIFORNIA

Comments: Young Hall consists of five separate buildings (see the plan view showing buildings CG-1, CG-1, C-2, and the East Wing). Separate reports have been prepared for each building.

The lateral force resisting system of Building C-1 in each orthogonal direction consists of 10"-12" thick perimeter reinforced concrete shear walls. Refer to the calculations for the typical floor plan view and wall elevation views.



Structural deficiencies per the Tier 1 evaluation include overstressed shear walls in both orthogonal directions as well as insufficient confinement of secondary components for deflection compatibility.

BACKGROUND INFORMATION

Site Information

16) Site Class (A – F) and Basis of Assessment

(a) Site Class: D

(b) Site Class Basis: Unknown (Default)

(c) Site Class Company: None(d) Site Class Report Date: None(e) Site Class Ref Page No.: None

17) Geologic Hazards

(a) Fault Rupture (Yes, No or Unknown) and Basis of Assessment: No, CGS Maps

(b) Liquefaction (Yes, No or Unknown) and Basis of Assessment: No, CGS Maps

(c) Landslide (Yes, No or Unknown) and Basis of Assessment: No, CGS Maps

18) Site-specific Ground Motion Study? (Yes or No) No

Seismic design acceleration parameters of interest:	
For BSE-1N	1.633 and 0.828
For BSE-1E	0.897 and 0.517

19) Estimated Fundamental Period (seconds)

(a) Longitudinal: 0.43(b) Transverse: 0.43

- 20) Falling Hazards Assessment Summary: There is a potential for spalling of the brick veneer (typically 5" thick)
- 21) Structural Non-Compliances/Findings Significantly Affecting Rating Determination Summary Significant Structural Deficiencies, Potentially Affecting Seismic Performance Rating Designation:
 - (a) Lateral System Stress Check (wall shear, column shear or flexure, or brace axial as applicable): Yes, wall shear stress deficiency noted
 - (b) Load Path: No deficiency noted
 - (c) Adjacent Buildings: Yes, deficiency noted. The 5" gap provided between Building C-1 and each building adjacent to it is less than the required separation per the Tier 1 checklist (see the Tier 1 CP Basic Configuration Checklist for more details).
 - (d) Weak Story: No deficiency noted
 - (e) Soft Story: No deficiency noted
 - (f) Geometry (vertical irregularities): No deficiency noted
 - (g) Torsion: No deficiency noted
 - (h) Mass Vertical Irregularity: No deficiency noted
 - (i) Cripple Walls: Not Applicable



(j) Wood Sills (bolting): Not Applicable

(k) Diaphragm Continuity: No deficiency noted

(I) Openings at Shear Walls (concrete or masonry): No deficiency noted

(m) Liquefaction: No(n) Slope Failure: No

(o) Surface Fault Rupture: No

(p) Masonry or Concrete Wall Anchorage at Flexible Diaphragm: Not Applicable

(q) URM wall height to thickness ratio: Not Applicable

(r) URM Parapets or Cornices: Not Applicable

(s) URM Chimney: Not Applicable

(t) Heavy Partitions Braced by Ceilings: No deficiency noted

(u) Appendages: No deficiency noted

22) Brief Description of Anticipated Failure Mechanism

Shear cracking and flexural compression failure of shear walls. Shear failure of lightly confined concrete gravity columns due to deformation compatibility drift.

23) Seismic Retrofit Concept Sketches/Description (only required for buildings rated V or worse) Increase confinement of concrete columns via FRP overlay, added shear wall strength using thickened cross-section or FRP overlay, or energy dissipation to reduce drift.

Building Report Appendices

- A) ASCE 41-17 Tier 1 Checklists (Structural only)
- B) Quick Check Calculations